

Tack fuse Tack firing paint (enamel) to surface of glass
full°/hr to 1300° / 0

Full Fuse (Quilted Tiles)

Seg 1 400°/hr to 1000° hold 2 min

Seg 2 1000° /hr to 1465° hold 2 min

Seg 3 full /hr to 960° hold 20 min

Dimensional Fuse (Fun & Funky Jewelry)

Seg 1- 400°/hr to 1000° hold 5 min

Seg 2 - 1000°/hr to 1410° hold 0